

## Aluminium crack testing

Item no.	311051	311050	311052
Description	Cleaner for test agent 400 ml	Penetration test fluid for aluminium cracks - 400 ml	Developer for test agent 400 ml
QTY /	1 pc. /	1 pc. /	1 pc. /

### Test Stage 1 + 3 | Cleaner

The surface must be carefully cleaned **before and after** applying the penetration fluid.

### Test stage 2 | Indicator

Spray on red liquid, waiting time approx. 15-20 minutes, after 20 min. wipe off with a cloth.

### Test stage 3 | Developer

Spray the entire surface completely thin. Application time 20-30 min.



## Temperature indication


Item no.	311062	311063	311064
Description	temperature indicator   stick red melting point <b>100 °C</b>	temperature indicator   stick green melting point <b>204 °C</b>	temperature indicator   stick yellow melting point <b>400 °C</b>
QTY /	1 pc. /	1 pc. /	1 pc. /

Application:  
Mark the workpiece before or during heating. When the nominal temperature is reached, the marking melts (runs) and is clearly visible.



Item no.	311060	311061	311065
Description	Temp indicator strip with 6 points up to <b>160 °C</b>	Temp indicator strip with 6 points up to <b>127 °C</b>	temperature indicator   stick blue melting point <b>500 °C</b>
QYT /	10 pcs. /	10 pcs. /	1 pc. /

Apply indicator by applying light pressure to clean, grease-free surface. When the temperature threshold is reached, the color of the measuring point changes.



## Landskit 2000 - mobile welding protection curtains stand


Item no. 881220

Fixed protective wall for welding work.  
Lamella length 1800 mm with running clamps  
ground clearance approx. 300 mm



colour orange

tested & certified  
DIN EN  
1598



An advantage of welding curtains in orange is their transparency, which allows you to observe the welding process without suffering radiation damage to your eyes.